

List of Different Parts of Deflection IC (CMC-531X/541X)

Daewoo has provided this list of parts to replace the hard to find, IC501. If you replace IC501, you will also need to replace R007 and C011.

LOC.	Part-Code	Part Name and Description	Part-Code	Part Name and Description
IC501	IKB2511---	IC KB2511	ITDA9109A-	IC TDA9109A
R007	RD-AZ822J-	R CARBON FILM 1/6 8.2K Ohm J	RD-AZ333J-	R CARBON FILM 1/6 33K Ohm J
C011	CMXM2A822J	C MYLAR 100V 8200PF J (TP)	CMXM2A222J	C MYLAR 100V 2200PF J (TP)